

KEITHLEY

Low Level Seminar


4 Steps to Precision Measurements

www.Keithley.com
1-888-KEITHLEY

KEITHLEY

A Greater Measure of Confidence

Measurement System



KEITHLEY

A Greater Measure of Confidence

What limits your Results

- *The material or device under test (DUT) itself?*
- *The connections between the DUT and instruments (including cables, fixtures, switching, etc.)?*
- *The measuring instrument?*

4 Step Measurement Process

1. Define required measurement quality
 - Accuracy, Repeatability, Timing, ...
2. Design measurement system
 - Select equipment and fixtures
3. Build and verify performance
 - Techniques to improve measurements
4. Use system to gather desired information

KEITHLEY

A Greater Measure of Confidence

4 Step Measurement Process

1. Define required measurement quality
 - Accuracy, Repeatability, Timing, ...
2. Design measurement system
 - Select equipment and fixtures
3. Build and verify performance
 - Techniques to improve measurements
4. Use system to gather desired information

KEITHLEY

A Greater Measure of Confidence

Measurement Basics

- Resolution
- Sensitivity
- Accuracy
- Repeatability



Resolution

- The smallest *portion* of the signal that can be observed
- 12-bit resolution = 1 part in 4096
- 4 1/2 digits = 1 part in 20000 counts (00000 to 19999)
- 7 1/2 digits = 1 part in 20,000,000 counts (00000000 to 19999999)

KEITHLEY

A Greater Measure of Confidence

Sensitivity

- The smallest *change* that can be detected
- Specified in units of the measured value
 - Volts, ohms, degrees
- Examples:
 - 3 1/2 digits (2000) on 2V range = 1 mV
 - 4 1/2 digits (20000) on 2Ω range = 100 μΩ
 - 16-bit (65536) A/D on 2V range = 30 μV
 - 8 1/2 digit on 200 mV range = 1 nV


KEITHLEY

A Greater Measure of Confidence

Accuracy

- Absolute accuracy
 - A measure of the closeness of agreement between a measured value and that of a primary standard value
- Relative accuracy
 - A measure of the closeness of agreement between a measured value and that of a locally established reference value


Accuracy



KEITHLEY

A Greater Measure of Confidence

Resolution, Accuracy, Repeatability




Resolution Accuracy Repeatability

KEITHLEY

A Greater Measure of Confidence

Resolution, Accuracy, Repeatability



Resolution

Accuracy

Repeatability



Low


Low

Low

KEITHLEY

A Greater Measure of Confidence

Resolution, Accuracy, Repeatability



Resolution

Accuracy

Repeatability



Low

Low

High



Low


Low

Low

KEITHLEY

A Greater Measure of Confidence

Resolution, Accuracy, Repeatability




Resolution Accuracy Repeatability

| | | | |
|---|------|-----|------|
| ● | High | Low | High |
| ● | Low | Low | High |
| ● | Low | Low | Low |

KEITHLEY

A Greater Measure of Confidence

Resolution, Accuracy, Repeatability



Resolution Accuracy Repeatability

| | | | |
|---|------|------|------|
| ● | High | High | High |
| ● | High | Low | High |
| ● | Low | Low | High |
| ● | Low | Low | Low |

KEITHLEY

A Greater Measure of Confidence

4 Step Measurement Process

1. Define required measurement quality
 - Accuracy, Repeatability, Timing, ...
2. Design measurement system
 - Select equipment and fixtures
3. Build and verify performance
 - Techniques to improve measurements
4. Use system to gather desired information

KEITHLEY

A Greater Measure of Confidence

Design measurement

- Keithley's other low level seminars talk about appropriate selection of ammeters and voltmeters
- Understanding of specs of the instrumentation is key for success


KEITHLEY

A Greater Measure of Confidence

How to read specs

- Accuracy
 - Offset error vs Gain error
 - Temperature coefficient
- Sensitivity
 - Noise vs resolution
- Timing
 - Settling Time vs Rise Time


Accuracy



KEITHLEY

A Greater Measure of Confidence


Accuracy



KEITHLEY

A Greater Measure of Confidence


Accuracy



KEITHLEY

A Greater Measure of Confidence


Accuracy



KEITHLEY

A Greater Measure of Confidence


Linearity



KEITHLEY

A Greater Measure of Confidence


Temperature Coefficient



KEITHLEY

A Greater Measure of Confidence

Temperature Coefficient



KEITHLEY

A Greater Measure of Confidence

Instrumentation Error

- Accuracy = \pm (% reading + % range)
= \pm (gain error + offset error)
- For example, DMM 2V range:
Accuracy = \pm (0.03% of reading + 0.01% range)
- For a 0.5V input:
Uncertainty = \pm (0.03% x .5V + .01% x 2.0V)
= \pm (.00015V + .00020V)
= \pm 350 μ V
- Reading = .49965 to .50035

KEITHLEY

A Greater Measure of Confidence

Instrumentation Error - DMM Example

- DMM, 6 1/2 digit, 2V range (2.000000)

Accuracy

$$= \pm (0.003\% \text{ reading} + 0.001\% \text{ range})$$

$$= \pm (30 \text{ ppm readings} + 10 \text{ ppm range})$$

$$= \pm (0.003\% \text{ reading} + 20 \text{ counts})$$

Uncertainty @ .5V

$$= \pm (.000015 + .000020)$$

$$= \pm .000035\text{V}$$

$$= \pm 35 \mu\text{V}$$

KEITHLEY

Instrumentation Error – Data Acquisition Board Example

- Analog input board, 12 bit, 2V range

Accuracy

$$= \pm (0.01\% \text{ reading} + 1 \text{ LSB})$$

$$= \pm (100\text{ppm} + 1 \text{ bit})$$

Uncertainty @ .5V

$$= \pm \left(.000050 + \frac{2.0}{4096} \right)$$

$$= \pm (.000050 + .000488)$$

$$= \pm .000538$$

$$= \pm 538 \mu\text{V}$$

KEITHLEY

Sensitivity

- The smallest observable change may be limited either by noise or by digital resolution
- Instrument Noise is often specified
 - Peak-to-peak, RMS, in some bandwidth
- If not specified, could be measured:
 - Voltmeters/Ohmmeters: Shorted Input
 - Ammeters: Open (Shielded) Input

KEITHLEY

A Greater Measure of Confidence

Timing

- Rise Time:
 - 10% – 90%
 - 2.2 time constants (2.2 X RC)
- Settling Time:
 - Specified as time for measurement circuitry to settle to within 1% (or .1%) of final value

4 Step Measurement Process

1. Define required measurement quality
 - Accuracy, Repeatability, Timing, ...
2. Design measurement system
 - Select equipment and fixtures
3. Build and verify performance
 - Techniques to improve measurements
4. Use system to gather desired information

KEITHLEY

A Greater Measure of Confidence

Measurement System

Instrument

Cabling/
Interference

DUT/
Test Fixture


- We have picked appropriate equipment, cables, and fixtures
- We know the specs of the equipment
- Verify performance one step at a time

KEITHLEY

A Greater Measure of Confidence

Assemble system one piece at the time

- Start with the instrument, verify noise and error:
 - Voltage measurements: Short circuit input
 - Ammeter: Open circuit input




KEITHLEY

A Greater Measure of Confidence

Assemble system one piece at the time

- Start with the instrument, verify noise and error:
 - Voltage measurements: Short circuit input
 - Ammeter: Open circuit input
- ... Then include Cabling




KEITHLEY

A Greater Measure of Confidence

Assemble system one piece at the time

- Start with the instrument, verify noise and error:
 - Voltage measurements: Short circuit input
 - Ammeter: Open circuit input
- Include Cabling
- ... Then include the Test Fixture




KEITHLEY

A Greater Measure of Confidence

Assemble system one piece at the time

- Start with the instrument, verify noise and error:
 - Voltage measurements: Short circuit input
 - Ammeter: Open circuit input
- Include Cabling
- Then include the Test Fixture
- ... Then include the DUT




KEITHLEY

A Greater Measure of Confidence

Assemble system one piece at the time


- Start with the instrument, verify noise and error:
 - Voltage measurements: Short circuit input
 - Ammeter: Open circuit input
- Include Cabling
- Then include the Test Fixture
- Then include the DUT
- Check timing, reassess measurement speed goals



KEITHLEY

A Greater Measure of Confidence

Capacitance / Delay Time




Capacitance (and sometimes inductance) in the system often require that you delay measurements after a change in stimulus for a good measurement.

KEITHLEY

A Greater Measure of Confidence

Assemble system one piece at the time

- Start with the instrument, verify noise and error:
 - Voltage measurements: Short circuit input
 - Ammeter: Open circuit input
- Include Cabling
- Then include the Test Fixture
- Then include the DUT
- Check timing, reassess measurement speed goals



KEITHLEY

A Greater Measure of Confidence

If unacceptable errors or noise


- The step-at-a-time approach allows us to identify the location of the problem
- Previous seminars talk about measurement techniques:
 - Low voltage measurements: Thermal EMFs, Magnetic interference, Ground loops, ..
 - Low current measurement: Cable noise, Contamination effects, Shielding, Guarding, ..
 - Resistance measurements: Delta mode, Alternating Voltage Mode, ..

KEITHLEY

Reducing interference

- Interference introduces *AC and DC* errors in the measured signal.
 - The source of interference is often at the power line frequency, 50 or 60 Hz
- Remedy for these types of errors
 - Integration
 - Filtering


External Noise “Pick-up”



KEITHLEY

A Greater Measure of Confidence

Line-Cycle Integration



This ability to reject 60Hz noise at the input is called Normal Mode Rejection Ratio (NMRR).

1Vpp noise @ 60dB NMRR = 1mV error.

KEITHLEY

A Greater Measure of Confidence

Theoretical Limits of Measurement

The **DUT resistance** provides a fundamental limit to how well Vs or Is can be resolved:

$$V_n = \sqrt{4kTB R_{DUT}} \quad I_n = \sqrt{4kTB / R_{DUT}}$$

K - Boltzmann's constant

T - Absolute temperature of the source

B - Noise bandwidth in hertz

R - Resistance of the source in Ohms

KEITHLEY

A Greater Measure of Confidence

How to reduce V_n and I_n

- Reduce temperature
- Reduce the bandwidth:
 - Increasing response time of the instrument
 - Integration
 - Noise speed trade off

4 Step Measurement Process

1. Define required measurement quality
 - Accuracy, Repeatability, Timing, ...
2. Design measurement system
 - Select equipment and fixtures
3. Build and verify performance
 - Techniques to improve measurements
4. Use system to gather desired information

KEITHLEY

A Greater Measure of Confidence

Use system to gather desired information

- On a regular basis, reassess system performance
- For how long can I trust my instrument's specs
 - Specified accuracy changes with time
- Calibration - adjustment of a device to within a specified percent of a known standard (NIST)
- Component drift determines a manufacturer's accuracy specs



A Greater Measure
of Confidence



A Greater Measure of Confidence